



SWI-ECL2 Tech Bulletin

Not all radio control functions control the AVN-2210P radio.

Description: The LED flashes after programming all SWC buttons however the radio is not being controlled properly.

Solution: Connect the Brown and White radio control wires to the Eclipse radio opposite of the connection instructions. This is ONLY for the AVN-2210p. Re-programming the SWC interface is not necessary.