



Fitting/selling GW51MO2

Do you have a factory CD changer?

AUDI MMI2 Colour

This is not an issue for Audi as the GW500 will work in and position in the ring.

AUDI MMI2 Basic (Red display)

Yes – The GW500 must be installed at the CDC as per 2A in the guide.

No – Fit at the back of the head unit. This can be connected anywhere on the ring also

BTA1500 is available for both of these products.

Extensions are available for dock in the centre console or glove box

BMW iDRIVE and PRO

Yes – The GW500 will always have to fitted at the CD Changer. As Per 2A in the guide.

No – The CD Changer will have to be activated at the dealer for the GW500 to work

3 series – CD Changer will be either in the head unit or in the boot left hand side

5/6 Series – The CD Changer is in the glove box (DIN SIZE)

7 Series – The CD Changer is in the dash passenger side

- If the vehicle is newer than 2007 the text will be available
- If older than 2007 the KMP3 will have to be enabled at a dealer.

BTA is available for the this vehicle

PORSCHE – PCM and CDR

Yes – The GW500 will always have to fitted at the CD Changer. As Per 2A in the guide.

No – The GW500 has to be installed at the rear of the head unit. The last on the Ring, Porsche have all the devices numbered and if the GW500 is in the wrong spot. The Error message will be shown.

Text is only available on the PCM2 & 2.1.

BTA is only available for PCM not CDR head units (PCM has the screen and GPS)

MERCEDES, Audio 20/50 and Command NTG1 and NTG2

Yes – The GW500 will always have to fitted at the CD Changer. As Per type 2A in the guide.

No – The GW500 has to be installed at the rear of the head unit last on the ring. If the vehicle has no other components on the ring, this will have to have the ring activated at a dealer. (There will be no Light activity on the ring at all).

BTA is available for this vehicle

VOLVO with floating dash (Fibre optic system)

Yes – The GW500 will always have to fitted at the CD Changer. As Per 2A in the guide.

No – The product is not compatible

SAAB – Fibre vehicles only 2004-2006

Yes – The GW500 will always have to fitted at the CD Changer. As Per 2A in the guide.

No – The product is not compatible

NO TEXT

In all cases the unit must be put into GW MODE to enable the text.

- Bmw – If older than 2007 the KMP3 will have to be enabled at a dealer.
- Mercedes Comand – The Text activation process on the instruction guide needs to be followed.
- (Toggle aux box and select + paging)
- Mercedes 20/50 – No text is available
- Porsche – Text only available on PCM2 & 2.1 NOT CDR
- Volvo – Text will be available, please switch on RDS text and MP3 text on the head unit menu.